

QUICK FACTS

- Goal:** Reconditioning of compactor and bin, to as new look.
- Solution:** Strip back the graffiti, repair panels, apply rust-proof paint & top coat.
- Result:** Reconditioning carried out in three days with renovated unit back to as new condition.

THE ISSUE

A B Equipment received a call from the Maintenance department of a Client requesting repairs to the Compactor and Bin at the Supermarket at Hope Island on the Gold Coast. These items had been vandalised and graffitied.

BEFORE PHOTOS



Together **E**veryone **A**chieves **M**ore

THE RESOLUTION

Our Client accepted a quotation for the removal of graffiti and repainting of the compactor and bin by A B Equipment.

A B Equipment's experienced team planned this task to be completed at our Client's premises with minimum down-time for the compactor and bin involved.

The team at A B Equipment stripped back the graffiti, repaired the panels on the compactor and bin, applied a rust-proof undercoat which took overnight to dry thoroughly.

The compactor and bin then received a rust-proof paint bringing it back to looking like new. Our Client and the Shopping Centre Management approved the paint colour.

Repairs were completed in three days with the renovated unit back to as new condition. Our Client and Shopping Centre Management were most pleased with the project outcome.

AFTER PHOTOS



Together **E**veryone **A**chieves **M**ore