



CASE STUDY NO 18

8 Pallet Scissor Lift

QUICK FACTS

- Goal:** Install a eight pallet scissor lift into a confined area.
- Solution:** Place two units into the area, then attach them as one.
- Result:** By placing two units into the confined area and then attaching them as one, this gave the customer the eight pallet scissor lift they were requiring.

THE ISSUE

An eight Pallet Scissor lift was required with minimal space within the stockroom due to the stockroom layout. Due to the positioning of the doorway opening, the unit could not be installed as a one-piece unit. The unit also required a longer reach on the flap, due to the wall that was needed to be cleared before being able to sit on the trailers to unload their product.

THE RESOLUTION

A B Equipment was able to supply and place two units and attach them as one, therefore, giving the customer an eight pallet Scissor Lift. A B Equipment also installed a 1100mm flap fitted to the side of the scissor lift. This gave the customer the reach required and a Lift with greater lifting capacity; allowing us to position the Scissor Lift table in a way that allowed clear access and pathways within the stockroom.

All works were completed on time and took less than five days to install without any issues by our Melbourne based Technicians, Alan Fisher and Brett Grinstead. After a training session with both staff and our customer's representatives, the unit has performed flawlessly, and the staff are pleased and

Together Everyone Achieves More

AFTER PHOTOS



Together **E**veryone **A**chieves **M**ore