



CASE STUDY NO 19

8 Pallet Scissor Lift with insulated panel lift door & collapsible dock shelter

QUICK FACTS

- Goal:** Install a eight pallet scissor lift into an area difficult to access.
- Solution:** Lift both sections in separately then join them in place.
- Result:** Equipment supplied & installed utilising a crane and then assembled in place.

THE ISSUE

An 8 Pallet Scissor Lift, with insulated panel lift door, and collapsible dock shelter had to be installed in a difficult to access area. As a last-minute request by the customer, the short time frame was a challenge.

THE RESOLUTION

A B Equipment was able to supply an 8 Pallet Scissor Lift with a 900mm flap fitted. We were able to achieve installation by utilising a Franna Crane to lift both sections of the scissor lift into place, and then assemble it. Doing so, allowed an issue-free assembly and a smooth installation of the collapsible dock shelter, complete with steel-faced dock bumpers.

Our Melbourne-based Technicians, Alan Fisher and Brett Grinstead completed the project, along with providing training for the relevant employees of our client. The unit has performed flawlessly.

The client's employees, and management, are delighted with the installation, the operation and functionality of the unit.

Together **E**veryone **A**chieves **M**ore

AFTER PHOTOS



Together **E**veryone **A**chieves **M**ore